

**Technician's Pricing Guide  
NORTH RESIDENTIAL**

**Collier Consulting Group**

# Table Of Contents

---

## Service

Batteries (BT)  
Bearings and Shafts (BG)  
Belts (BE)  
Boiler Repairs (BR)  
Carbon Monoxide Detection (CT)  
Carrier Circuit Boards (C9)  
CARRIER Repairs (RA)  
Circuit Breakers--Commercial (CK)  
Circuit Breakers--Residential (CZ)  
Condensate Drain (CD)  
Condensate Pumps (CC)  
Diagnostic Charges (DG)  
Disconnects (DI)  
Drain Pans (DP)  
Electronic Ignition (EN)  
Fan Centers (FC)  
Fan Limits (F2)  
Fan Relays (FR)  
Filters (FE)  
Float Switches (FS)  
Gas Connectors (GC)  
Gas Heating (GH)  
Gas Valves (GV)  
HEIL/WHIRLPOOL Repairs (HE)  
Humidifiers (HD)  
Hydronic Heat (HY)  
LENNOX Repairs (LE)  
Limit Switches (LM)  
Line Driers (LD)  
LUXAIRE Repairs (LA)  
Miscellaneous Repairs (MI)  
Motors (MO)  
Oil Repairs (LO)  
Pilot Burners (PB)  
Pilot Tubing (PT)  
Precision Tune Ups (PS)  
Recover/Reclaim (RR)  
RHEEM/RUUD Repairs (RU)

# Table Of Contents

---

## Service






- Starting Devices (SD)
- Starting Relays (SL)
- Thermocouples (RM)
- Thermostat Wire (RW)
- Thermostats (HT)
- Time Delays (MD)
- TRANE Furnace Repairs (TF)
- Trane/AmStd Defrost Controls (AE)
- Transformers (SF)
- Unknown Repair Pricing (UK)
- Valves--Expansion, Reversing and Gas (V9)



# Collier Consulting Group



Your Neighborhood HVAC Professional









Service (S)		Batteries (BT)		
		SEA	Regular	Seniors
<b>3SBT-A0978</b>	<b>1 Replace D-CELL BATTERY in home appliance</b>			
		\$6.92	\$8.32	\$7.66
1 79401	D-CELL BATTERY			
	Notes: n/a			
<b>3SBT-A0979</b>	<b>1 Replace C-CELL BATTERY in home appliance</b>			
		\$6.67	\$8.03	\$7.38
1 79402	C-CELL BATTERY			
	Notes: n/a			
<b>3SBT-A0980</b>	<b>1 Replace AA-BATTERY in home appliance</b>			
		\$3.61	\$4.43	\$3.96
1 79403	AA-BATTERY			
	Notes: n/a			
<b>3SBT-A0981</b>	<b>1 Replace AAA-BATTERY in home appliance</b>			
		\$5.02	\$6.08	\$5.53
1 79404	AAA-BATTERY			
	Notes: n/a			
<b>3SBT-A0982</b>	<b>1 Replace 9-VOLT BATTERY in home appliance</b>			
		\$9.80	\$11.71	\$10.88
1 79405	9-VOLT BATTERY			
	Notes: n/a			



# Collier Consulting Group

Your Neighborhood HVAC Professional






Service (S)		Bearings and Shafts (BG)		
		SEA	Regular	Seniors
<b>3SBG-Q9076</b>	<b>95</b>	<b>Replace Bearing, rubber cushioned. O.75 bore</b>		
		\$275.46	\$340.61	\$300.42
1 BRG00654		BEARING, RUBBER CUSHIONED, .75 BORE, PERMANENTLY LUBED, SET SCREW LOCKING DEVICE		
		Notes: n/a		
<b>3SBG-Q9077</b>	<b>30</b>	<b>Replace Shaft; 1" Diam, with Blower apart</b>		
		\$194.34	\$233.85	\$214.85
1 SHF02348		SHAFT; 1 INCH DIA. 23 INCHES LONG		
		Notes: n/a		
<b>3SBG-Q9078</b>	<b>90</b>	<b>Replace Shaft; 1" Diam, without Blower apart</b>		
		\$319.34	\$391.35	\$349.85
1 SHF02348		SHAFT; 1 INCH DIA. 23 INCHES LONG		
		Notes: n/a		
<b>3SBG-Q9079</b>	<b>30</b>	<b>Replace Shaft; 0.75" Diam, with Blower apart</b>		
		\$221.48	\$265.78	\$245.18
1 SHF01308		SHAFT; .750 DIAMETER X 17.11 LONG		
		Notes: n/a		
<b>3SBG-Q9080</b>	<b>90</b>	<b>Replace Shaft; 0.75" Diam, without Blower apart</b>		
		\$346.48	\$423.28	\$380.18
1 SHF01308		SHAFT; .750 DIAMETER X 17.11 LONG		
		Notes: n/a		
<b>3SBG-Q9081</b>	<b>30</b>	<b>Replace Motor Shield</b>		
		\$114.89	\$140.39	\$126.06
1 SHD00040		SHIELD; MOTOR		
		Notes: n/a		
<b>3SBG-Q9082</b>	<b>45</b>	<b>Replace Bearing with Blower apart</b>		
		\$139.41	\$171.85	\$152.28
1 BRG00052		BEARING; 1 IN. BORE		
		Notes: n/a		
<b>3SBG-Q9083</b>	<b>90</b>	<b>Replace Bearing without Blower apart</b>		
		\$233.16	\$289.97	\$253.53
1 BRG00052		BEARING; 1 IN. BORE		
		Notes: n/a		



# Collier Consulting Group



Your Neighborhood HVAC Professional

Service (S)		Belts (BE)		
		SEA	Regular	Seniors
<b>3SBE-A1185</b>	<b>15 Replace BELT;V (FHP), Up to 48"</b>			
		\$49.75	\$61.14	\$54.42
1 B00005	BELT;V (FHP), Up to 48"			
	Notes: n/a			
<b>3SBE-A1186</b>	<b>15 Replace BELT;V (FHP), Larger than 48"</b>			
		\$52.29	\$64.13	\$57.26
1 B00007	BELT;V (FHP), Larger than 48"			
	Notes: n/a			
<b>3SBE-A1187</b>	<b>15 Replace BELT;V (FHP), With Motor Replacement</b>			
		\$55.05	\$67.38	\$60.35
1 B00008	BELT;V (FHP), Other			
	Notes: n/a			



# Collier Consulting Group

Your Neighborhood HVAC Professional



Service (S)		Boiler Repairs (BR)		
		SEA	Regular	Seniors
<b>3SBR-T0160</b>	<b>45 Replace ID Motor</b>			
		\$375.98	\$450.16	\$416.68
1 3832093	I.D. Motor, FO, WM, VHE Series			
	Notes: n/a			
<b>3SBR-T0162</b>	<b>20 Replace Ignition Control</b>			
		\$218.99	\$261.11	\$243.18
1 3834023	Ignition Module for WM, HE Series			
	Notes: n/a			
<b>3SBR-T0164</b>	<b>30 Replace Gas Valve with Gold Control Module</b>			
		\$129.74	\$157.86	\$142.65
1 3834045	GV Kit WM Gold Control Module			
	Notes: n/a			
<b>3SBR-T0166</b>	<b>30 Replace Gas Valve</b>			
		\$258.71	\$309.59	\$286.80
1 3834063	HE/VHE LP Gas Valve			
	Notes: n/a			
<b>3SBR-T0168</b>	<b>20 Replace Ignitor</b>			
		\$108.91	\$131.61	\$120.15
1 3834107	GV/HEII/AHE Ignitor Kit			
	Notes: n/a			
<b>3SBR-T0170</b>	<b>20 Replace Flame Sensor</b>			
		\$168.90	\$202.19	\$187.21
1 3834154	Mercury Flame Sensor WM with Auto Pilot			
	Notes: n/a			
<b>3SBR-T0172</b>	<b>30 Replace Circulating Pump Coupling</b>			
		\$85.37	\$105.65	\$93.06
1 BG-33	B&G Circulating Pump Coupling, Spiral Link Style			
	Notes: n/a			
<b>3SBR-T0174</b>	<b>30 Replace Circulating Pump Impeller-Series 189</b>			
		\$95.34	\$117.39	\$104.21
1 L37-189	B&G Non-Ferrous Impeller			
	Notes: n/a			
<b>3SBR-T0176</b>	<b>30 Replace Circulating Pump Impeller-Series 193</b>			
		\$190.71	\$229.59	\$210.80
1 L37-193	B&G Non-Ferrous Impeller, 193			
	Notes: n/a			



# Collier Consulting Group

Your Neighborhood HVAC Professional



Service (S)		Boiler Repairs (BR)		
		SEA	Regular	Seniors
<b>3SBR-T0178</b>	<b>15</b>	<b>Replace Air Vent for Baseboard</b>		
		\$43.32	\$53.58	\$47.24
1 L37-203		Air Vent for Baseboard		
		Notes: n/a		
<b>3SBR-T0180</b>	<b>20</b>	<b>Replace Relief Valve</b>		
		\$121.85	\$146.83	\$134.61
1 L37-316		Relief Valve, 3/4 by 3/4, 30# BlowOff		
		Notes: n/a		
<b>3SBR-T0182</b>	<b>20</b>	<b>Replace Circulating Pump Coupling</b>		
		\$66.62	\$81.86	\$72.89
1 L37-350		B&G Circulating Pump Coupling		
		Notes: n/a		
<b>3SBR-T0185</b>	<b>20</b>	<b>Replace Auto Air Vent</b>		
		\$101.54	\$122.94	\$111.92
1 L37-831		Auto Air Vent		
		Notes: n/a		
<b>3SBR-T0187</b>	<b>45</b>	<b>Replace Auto Fill Reducing Valve</b>		
		\$178.98	\$218.40	\$196.51
1 L37-832		B&G Pressure Reducing Valve, 12# Set, 1/2 inch brass		
		Notes: n/a		
<b>3SBR-T0189</b>	<b>45</b>	<b>Replace 24 volt Zone Valve</b>		
		\$178.98	\$218.40	\$196.51
1 L37-904		Zone Valve, 24 volt		
		Notes: n/a		
<b>3SBR-T0192</b>	<b>30</b>	<b>Replace Pump Flange Gaskets</b>		
		\$80.85	\$100.34	\$88.01
1 L38-390		TACO Pump Flange Gaskets, 005-009 Series Pumps		
		Notes: n/a		
<b>3SBR-T0194</b>	<b>45</b>	<b>Replace 24 volt Zone Valve</b>		
		\$246.95	\$298.37	\$272.48
1 L38-686		Zone Valve, 24 volt, 3/4 sweat		
		Notes: n/a		
<b>3SBR-T0196</b>	<b>45</b>	<b>Replace Ball Valve for Low water cut-off</b>		
		\$209.27	\$254.04	\$230.36
1 L38-713		Ball Valve for Low Water CutOff, McDonnell Miller		
		Notes: n/a		













# Collier Consulting Group

Your Neighborhood HVAC Professional






Service (S)		Boiler Repairs (BR)		
		SEA	Regular	Seniors
<b>3SBR-T0198</b>	<b>45 Replace Circulating Motor and Pump</b>			
		\$342.26	\$410.50	\$379.00
1 L86-074	B&G Motor and Pump			
	Notes: n/a			
<b>3SBR-T0200</b>	<b>45 Replace Bearing Assembly</b>			
		\$205.85	\$250.01	\$226.54
1 L86-078	B&G Bearing Assembly			
	Notes: n/a			
<b>3SBR-T0203</b>	<b>30 Replace Backflow Preventer</b>			
		\$121.25	\$147.87	\$133.16
1 R54-574	Backflow Preventer			
	Notes: n/a			
<b>3SBR-T0205</b>	<b>30 Replace Circulating Pump Switching Relay</b>			
		\$224.88	\$269.79	\$248.99
1 RA89A1074	Circulating Pump Switching Relay			
	Notes: n/a			
<b>3SBR-T0230</b>	<b>30 Bleed Air from System30</b>			
		\$62.50	\$78.75	\$67.50
	Notes: n/a			
<b>3SBR-T0245</b>	<b>45 Bleed Air from System45</b>			
		\$93.75	\$118.13	\$101.25
	Notes: n/a			
<b>3SBR-T0260</b>	<b>60 Bleed Air from System60</b>			
		\$125.00	\$157.50	\$135.00
	Notes: n/a			
<b>3SBR-T0270</b>	<b>60 Boiler Tune-Up</b>			
		\$125.00	\$157.50	\$135.00
	Notes: n/a			



# Collier Consulting Group



Your Neighborhood HVAC Professional

Service (S)		Carbon Monoxide Detection (CT)		
		SEA	Regular	Seniors
<b>3SCT-A0001</b>	<b>8 Carbon Monoxide Detector--Plug In</b>			
		\$67.67	\$81.00	\$75.00
1 06011	CARBON MONOXIDE ALARM PLUG IN			
	Notes: n/a			
<b>3SCT-A0983</b>	<b>10 Heads Up Carbon Monoxide Detector Card</b>			
		\$34.93	\$42.83	\$38.25
1 79529	HEADS UP CO-2 DETECTOR			
	Notes: n/a			
<b>3SCT-Q3149</b>	<b>10 Install CO-Experts Carbon Monoxide Detector</b>			
		\$199.23	\$236.13	\$221.89
1 CO2002	CO-EXPERTS 2002 CARBON MONOXIDE ALARM			
	Notes: n/a			



# Collier Consulting Group

Your Neighborhood HVAC Professional










Service (S)		Carrier Circuit Boards (C9)		
		SEA	Regular	Seniors
<b>3SC9-A8441</b>	<b>30 Replace Carrier HK42FZ010 Circuit Board</b>			
		\$320.56	\$382.35	\$355.92
1 HK42FZ010	CARRIER CIRCUIT BOARD, HK42FZ010			
	Notes: n/a			
<b>3SC9-A8442</b>	<b>30 Replace Carrier HH84AA017 Circuit Board</b>			
		\$194.11	\$233.59	\$214.60
1 HH84AA017	CARRIER CIRCUIT BOARD, HH84AA017			
	Notes: n/a			
<b>3SC9-A8443</b>	<b>30 Replace Carrier HH84AA020 Circuit Board</b>			
		\$191.49	\$230.50	\$211.66
1 HH84AA020	CARRIER CIRCUIT BOARD, HH84AA020			
	Notes: n/a			
<b>3SC9-A8444</b>	<b>30 Replace Carrier HH84AA021 Circuit Board</b>			
		\$209.97	\$252.24	\$232.32
1 HH84AA021	CARRIER CIRCUIT BOARD, HH84AA021			
	Notes: n/a			
<b>3SC9-A8445</b>	<b>30 Replace Carrier HK32FA006 Circuit Board</b>			
		\$195.36	\$235.05	\$215.99
1 HK32FA006	CARRIER CIRCUIT BOARD, HK32FA006			
	Notes: n/a			
<b>3SC9-A8446</b>	<b>30 Replace Carrier HK42FZ011 Circuit Board</b>			
		\$238.54	\$285.85	\$264.25
1 HK42FZ011	CARRIER CIRCUIT BOARD, HK42FZ011			
	Notes: n/a			
<b>3SC9-A8447</b>	<b>30 Replace Carrier HK42FZ012 Circuit Board</b>			
		\$308.61	\$368.29	\$342.56
1 HK42FZ012	CARRIER CIRCUIT BOARD, HK42FZ012			
	Notes: n/a			
<b>3SC9-A8448</b>	<b>30 Replace Carrier LH33CZ010 Circuit Board</b>			
		\$249.86	\$299.17	\$276.90
1 LH33CZ010	CARRIER CIRCUIT BOARD, LH33CZ010			
	Notes: n/a			
<b>3SC9-A8449</b>	<b>30 Replace Carrier LH33WP001 Circuit Board</b>			
		\$240.99	\$288.74	\$266.99
1 LH33WP001	CARRIER CIRCUIT BOARD, LH33WP001			
	Notes: n/a			



# Collier Consulting Group

Your Neighborhood HVAC Professional



Service (S)		Carrier Circuit Boards (C9)		
		SEA	Regular	Seniors
<b>3SC9-A8450</b>	<b>30 Replace Carrier LH33WP002 Circuit Board</b>			
		\$246.42	\$295.13	\$273.06
1 LH33WP002	CARRIER CIRCUIT BOARD, LH33WP002			
	Notes: n/a			
<b>3SC9-A8451</b>	<b>30 Replace Carrier LH33WP003 Circuit Board</b>			
		\$252.61	\$302.41	\$279.98
1 LH33WP003	CARRIER CIRCUIT BOARD, LH33WP003			
	Notes: n/a			
<b>3SC9-A8452</b>	<b>30 Replace Carrier CESO130003 Circuit Board</b>			
		\$100.02	\$122.89	\$109.43
1 CES0130003-01	CARRIER CIRCUIT BOARD, CES0130003-01			
	Notes: n/a			
<b>3SC9-A8453</b>	<b>30 Replace Carrier CESO130035 Circuit Board</b>			
		\$199.33	\$239.73	\$220.43
1 CES0130035	CARRIER CIRCUIT BOARD, CES0130035			
	Notes: n/a			
<b>3SC9-A8454</b>	<b>30 Replace Carrier CESO130057 Circuit Board</b>			
		\$226.41	\$271.58	\$250.69
1 CESO110057	CARRIER CIRCUIT BOARD, CESO110057			
	Notes: n/a			
<b>3SC9-A8455</b>	<b>30 Replace Carrier CESO130063 Circuit Board</b>			
		\$194.11	\$233.59	\$214.60
1 CESO110063	CARRIER CIRCUIT BOARD, CESO110063			
	Notes: n/a			
<b>3SC9-A8456</b>	<b>30 Replace Carrier 322848-751 Circuit Board</b>			
		\$143.05	\$173.52	\$157.53
1 322848-751	CARRIER CIRCUIT BOARD, 322848-751			
	Notes: n/a			